## **Idaho PUC Pipeline Safety Inspection Summary**

Inspector(s):	Ulmer/Russo	<b>Date(s):</b> Jun 18-21, 2018
Company/Owner:	Avista Utilities	Unit/OPID: Lewiston
0		
Inspection Type & Time (1 day, 0.5	5 day)	Total Inspection Days: 9
Standard: 5 Construction: 4 Tra	aining: (T)(D) Integrity	Management: Incident:
M/M: Follow-up:	OQ: Damage Pr	revention: D&A:
Inspection Summary		
A construction inspection was performed on Avista in the Lewiston/Moscow area.		
June 18, 2018: (2 Standard) Traveled to Lewiston, ID to conduct co		
A Curry Inc. crew (Avista Sub-contractor) was installing new service line from existing stub to a new residence. Installing a new 2" plastic service line to existing residence foundation on 24th Ave in Lewiston.		
Areas observed during this project were: excavation, pinching off, plastic pipe joining, hot tapping, pressure testing, purging, service line installation (tracer wire), riser placement and backfilling.		
June 20, 2018: (2 Construction)  A Curry Inc. crew (Avista Sub-contractor) was installing new service lines from existing stubs to two new residences. Installing a new 2" plastic service line to existing residence on Granville Rd in Moscow.		
Areas observed during this project were: pinching off, plastic pipe joining, hot tapping, pressure testing, purging, service line installation (tracer wire), riser placement and backfilling.		
<u>June 21, 2018:</u> (2 Standard) Traveled back to Boise, ID.		
June 22, 2018: (1 Standard post) Typed the construction inspection report. Completed IPUC forms.		
Attached: IPUC Form 1, Inspection Summary IPUC Form 4, Construction Inspections		
Corrective Action Required:  Yes No X	Follow-up Required	Yes No X by (date):
Inspector (Lead):	will the	Date: 22 June 2018
Reviewer:		Date: 15 2018